TECHNICAL
LIBRARY

AD

AD-E400 356

TECHNICAL REPORT ARLCD-TR-79009

EFFECT OF SURFACE EXPOSURE TIME (SET) ON STRENGTH OF ADHESIVE BONDS TO ALUMINUM

MARIE C. ROSS
NATALIA PETRIANYK
ELIZABETH A. GARNIS
RAYMOND F. WEGMAN
DAVID W. LEVI

AUGUST 1979



US ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

LARGE CALIBER

WEAPON SYSTEMS LABORATORY

DOVER, NEW JERSEY

APPROVED FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED.

The views, opinions, and/or findings contained in this report are those of the author(s) and should not be construed as an official Department of the Army position, policy or decision, unless so designated by other documentation.

Destroy this report when no longer needed. Do not return it to the originator.

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
Technical Report ARLCD-TR-79009	3. RECIPIENT'S CATALOG NUMBER
EFFECT OF SURFACE EXPOSURE TIME (SET) ON STRENGTH OF ADHESIVE BONDS TO ALUMINUM	S. TYPE OF REPORT & PERIOD COVERED 6. PERFORMING ORG. REPORT NUMBER
Marie C. Ross Raymond F. Wegman Natalia Petrianyk David W. Levi Elizabeth A. Garnis	8. CONTRACT OR GRANT NUMBER(s)
P. PERFORMING ORGANIZATION NAME AND ADDRESS ARRADCOM, LCWSL Applied Sciences Div (DRDAR-LCA-0) Dover, NJ 07801	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS AMCMS Code No. 612105H84001
1. CONTROLLING OFFICE NAME AND ADDRESS ARRADCOM, TSD STINFO (DRDAR-TSS) Dover, NJ 07801 4. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office)	12. REPORT DATE August 1979 13. NUMBER OF PAGES 15 15. SECURITY CLASS. (of this report)
	Unclassified 15. DECLASSIFICATION/DOWNGRADING SCHEDULE

17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

18. SUPPLEMENTARY NOTES

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Adhesive bonding Adverse environment Durability EC-2214 adhesive

Shear strength Surface exposure time

2024-T3 aluminum Weibull distribution

20. ABSTRACT (Continue on reverse eigh if necessary and identify by block number)

Surface exposure times (SET) at 23°C and 50% RH for 2024-T3 aluminum subsequently bonded with EC-2214 adhesive did not affect the bond strength for SET up to 30 days. SET at 54°C and 95 ± 5% RH gave much lower bond strengths that did not further change with increasing SET. The difference in strength is believed to be due to the formation of a hydrated aluminum oxide on the aluminum surface at 54°C and 95 \pm 5% RH. This hydrated oxide functions as a weak boundary layer.




TABLE OF CONTENTS

	Pag	e No.
Introduction		1
Results and Discussion		1
Experimental Procedures		2
Materials Surface Preparation Surface Exposure Before Bonding Bonding Procedure Method of Testing		2 2 2 2 3
Conclusions		3
References		3
Distribution List Figures	•	7
1 Comparison of strength data at two SET conditions.		5
2 Linear Weibull plots for two SET conditions.		6

INTRODUCTION

Earlier work on several aluminum alloys in these laboratories (refs. 1 and 2) has indicated that surface exposure times (SET) up to 30 days have little or no effect on subsequent adhesive bond strength and durability. At first glance these results would appear to be at odds with those of Smith and Kaelble (ref. 3). The latter authors found an initial marked drop in strength with SET, followed by a leveling-off. However, bond strengths in reference 3 were measured after using SET conditions of 54°C (129°F) and 95% RH. The SET conditions in references 1 and 2 were a better approximation of shop storage conditions (23°C (73°F) and 50% RH). In an effort to reconcile these results we have selected a system for which we had previously determined strength-SET data (refs. 1 and 2) and have carried out additional studies using 54°C and 95% RH as the SET conditions.

RESULTS AND DISCUSSION

The results for the 2024-T3/EC-2214 system are shown in figure 1. This figure shows clearly that there are marked differences in strength behavior, depending on which SET condition is used. At 23°C and 50% RH there appears to be no significant difference in strength for SET times up to 30 days. However, at 54°C and 95 \pm 5% RH SET conditions, strength initially falls off precipitously with SET and then levels off. These results generally are in accord with the earlier work (refs. 1 through 3).

It has been reported (refs. 4 and 5) that aluminum in hot water forms a hydrated oxide layer that is cohesively weak. Although adhesives bond readily to this oxide, it serves as a weak boundary layer and markedly reduces the resultant apparent strength of the bond. Under the elevated temperature and high humidity conditions of 54°C and 95% RH SET it seems reasonable to suppose that such a weak boundary layer is formed. This would be especially favored in the case of condensing humidity.* This weak boundary layer would then account for the marked strength reduction. Smith and Kaelble (ref. 3, pp 63 and 64) also report evidence for failure in a thick oxide layer after SET at 54°C and 95 through 100% RH. They also found indications that aging had caused a structural, as well as a thickness, change in the oxide.

^{*}W. Russell, private communication, 1979.

Linear Weibull distribution plots (ref. 6) are shown in figure 2. All of the data for each SET condition appear to fall within the same distribution. The correlation coefficients are 0.983 for SET at 23°C and 50% RH and 0.976 for SET at 54°C and 95% RH.

EXPERIMENTAL PROCEDURES

Materials

The aluminum alloy used was 2024-T3 bare, 0.025 cm (0.063 in.) thick.

EC-2214 is a modified epoxy paste manufactured by the Minnesota Mining and Manufacturing (3M) Company. It has a viscosity at room temperature suitable for trowel application. Curing is achieved at 121°C (250°F) in 40 minutes. It requires only contact pressure for joint formation.

Surface Preparation

The panels were washed with acetone and treated by immersion in a solution containing one part by weight (pbw) sodium dichromate, 10 pbw concentrated sulfuric acid, and 30 pbw deionized water. The solution temperature was 60°C (140°F), the immersion time 10 minutes. The treated panels were rinsed for 1 to 2 minutes in running tap water at 40°C (104°F), rinsed with deionized water at room temperature, and dried in an air-circulating oven at 60°C (140°F).

Surface Exposure Before Bonding

All but the control specimens were conditioned in a controlled environment of $54^{\circ}C$ ($129^{\circ}F$) and $95 \pm 5\%$ RH for periods of 2 hours, 4 hours, 15 hours, 24 hours, 48 hours, and 72 hours.

Bonding Procedure

The panels to be bonded were removed from their conditioning environments no sooner than 30 minutes before bonding. For the control specimens (0 hours conditioning) bonding was effected after the oven-drying. The EC-2214 was brought up to room temperature before application to the panels by means of a wooden tongue depressor. Curing was accomplished in jigs to control the overlap [1.27 cm (1/2 in.)].

Method of Testing

A Baldwin Universal Test Machine was used for load applications. The load rate was 16.5 MPa (2400 psi) per minute.

CONCLUSIONS

- 1. For the 2024-T3/EC-2214 system SET at 23°C and 50% RH gave strengths significantly higher than SET at 54°C and 95% RH.
- 2. The difference in strengths is believed to be due to formation of a hydrated aluminum oxide on the aluminum surface at 54°C and 95% RH. This hydrated oxide functions as a weak boundary layer.

REFERENCES

- D. W. Levi, W. C. Tanner, M. C. Ross, R. F. Wegman, and M. J. Bodnar, "Effect of Surface Exposure Time on Bonds to Aluminum," J. Applied Polymer Sci 20, p 1475 (1976).
- 2. D. W. Levi, "Durability of Adhesive Bonds to Aluminum,"

 J. Applied Polymer Sci: Applied Polymer Symposium 32, p 189

 (1977).
- 3. T. Smith and D. H. Kaelble, "Mechanisms of Adhesion Failure Between Polymers and Metallic Substrates: Aluminum 2024-T3 and Titanium 6A1-4V with HT424 Adhesive," AFML-TR-74-73, Wright Patterson AFB, Dayton, OH (1974).
- 4. S. Wernick and R. Pinner, The Surface Treatment and Finishing of Aluminum, Robert Draper Ltd, Teddington, G.B., p 197-198, 1964.
- 5. R. F. Wegman, "A Study of Adhesive Joint Failures by Evaporative Rate Analysis," Technical Report 3746, Picatinny Arsenal, Dover, NJ, 1968.
- 6. C. A. Moyer, J. J. Bush, and B. T. Ruley, "The Weibull Distribution Function for Fatigue Life," <u>Material Research and Standards 2</u>, p 405 (1962).




Figure 1. Comparison of strength data at two SET conditions.




Figure 2. Linear Weibull plots for two SET conditions

DISTRIBUTION LIST

Commander

U.S. Army Armament Research and

Development Command

ATTN: DRDAR-TSS (5)

DRDAR-LCA-OA (15)

DRDAR-LCN (5)

DRDAR-LCU (5)

DRDAR-QA (2)

DRDAR-TSF (2)

DRDAR-QAA

DRDAR-QAN

Dover, NJ 07801

Commander

U.S. Army Materiel Development and

Readiness Command

ATTN: DRCPP-PI

DRC-QA

5001 Eisenhower Avenue

Alexandria, VA 22304

Commander

U.S. Army Missile Research and

Development Command

ATTN: DRDMI-EAM, Mr. E. A. Verchot

Chief, Document Section

Huntsville, AL 35801

commander

U.S. Army Armament Materiel

Readiness Command

ATTN: DRSAR-LEP-L

DRSAR-ASF, Mr. H. Wohlferth

Rock Island, IL 61299

Commander

U.S. Army Electronics Command

ATTN: DRSEL-TL-ME, Mr. Dan Lichenstein

DRSEL-TL-ME, Mr. A. J. Raffalovich

DRSEL-TL-ME, Mr. G. Platau

DRSEL-PP-EM2, Ms. Sarah Rosen

Fort Monmouth, NJ 07703

Director

U.S. Army Tank-Automotive Research

and Development Command

ATTN: DRSTRA-KMD

Warren, MI 48090

Commander

U.S. Army Materials and Mechanics

Research Center

ATTN: DRXMR-FR, Dr. G. Thomas

DRXMR-PL

Technical Information Section

Watertown, MA 02172

Director

U.S. Army Industrial Base Engineering Activity

Rock Island Arsenal

ATTN: DRXIB-MT (3)

Rock Island Arsenal, IL 61299

Commander

USA Troop Support and Aviation Materiel

Readiness Command

ATTN: DRSTS-MEU(2) Mr. E. Dawson

DRSTS-ME(2) Mr. C. Sims

DRSTS-MEN(2) Mr. L. D. Brown

DRSTS-MEL(2) Mr. Bell

DRSTS-MET(2) Mr. Ceasar

P.O. Box 209, Main Office

St. Louis, MO 63166

Commander

Corpus Christi Army Depot

ATTN: DRSTS-MES (STOP 55) (2)

DRSTS-MESA, Mr. T. Tullos (2)

DRSTS-MESP, Mr. Bulloch

Corpus Christi, TX 78419

Commander/Director

Chemical Systems Laboratory

USA ARRADCOM, Bldg E5101

Aberdeen Proving Ground, MD 21010

Chief

Benet Weapons Laboratory

LCWSL, USA ARRADCOM

ATTN: DRDAR-LCB

DRDAR-LCB-TL

Watervliet, NY 12189

Director

U.S. Army Engineer Waterways

Experiment Station, P.O. Box 631

Corps of Engineers

ATTN: Mr. Hugh L. Green - WE SSS1

Vicksburg, MS 39180

Commander

U.S. Army Medical Bio-Engineering Research

and Development Laboratories

Fort Deterick

ATTN: Dr. C. Wade

Frederick, MD 21701

Commander

USA Aviation R&D Command

ATTN: DRDAV-EQA, Mr. W. McClane

4300 Goodfellow Blvd

St. Louis, MO 63120

Plastics Technical Evaluation Center

U.S. Army ARRADCOM

ATTN: Mr. H. Pebly

Mr. A. Landrock

Dover, NJ 07801

Commander

Harry Diamond Laboratories

ATTN: Mr. N. Kaplan

Mr. J. M. Boyd

Library

Washington, DC 20438

Commander

Chemical Systems Laboratory

ATTN: DRDAR-CLB-PM, Mr. Dave Schneck

Aberdeen Proving Ground, MD 21010

Commander Tobyhanna Army Depot ATTN: Mr. A. Alfano Tobyhanna, PA 18466

Director U.S. Army Ballistic Research Laboratory USA ARRADCOM Bldg 328 Aberdeen Proving Ground, MD 21005

Commander

U.S. Army Materiel Development and Readiness Command

ATTN: DRCPM-UA, Mr. C. Musgrave DRCPM-LH, Mr. C. Cioffi DRCPM-HLS-T, Mr. R. E. Hahn

P.O. Box 209 St. Louis, MO 63166

Commander
Natick Research and Development Command
Natick, MA 91760

Commander U.S. Army Engineer Research and

Development Labs Fort Belvoir, VA 22060

Department of the Navy Naval Air Systems Command ATTN: Mr. John J. Gurtowski (AIR 52032C) Washington, DC 20360

Naval Ordnance Station (NOSL) ATTN: Mr. W. J. Ryan, Code 5041 Southside Drive Louisville, KY 40214

Naval Avionics Facility
ATTN: Mr. B. D. Tague, Code D/802
Mr. Paul H. Guhl, D/033.3
21st and Arlington
Indianapolis, IN 46218

Commander
U.S. Naval Weapons Station
ATTN: Research and Development Division
Yorktown, VA 23491

Commander
Aeronautical Systems Division
ATTN: Mr. W. Scardino, AFML/MXE
Mr. T. J. Aponyi, Composite and Fibrous
Materials Branch, Nonmetallic Materials Div
Wright-Patterson Air Force Base, OH 45433

U.S. Army Air Mobility R&D Laboratory, Headquarters Advanced Systems Research Office ATTN: Mr. F. Immen, MS 207.5 Ames Research Center Moffet Field, CA 94035

Naval Ship Engineering Center ATTN: Mr. W. R. Graner, SEC 6101E Prince George's Center Hyattsville, MD 20782

Mare Island Naval Shipyard Rubber Engineering Section ATTN: Mr. Ross E. Morris, Code 134.04 Vallejo, CA 94592

Hanscom Air Force Base ATTN: Mr. R. Karlson, ESD/DE, Stop 7 HQ, ESD Bedford, MA 01731

Naval Air Development Center, Materials Laboratory ATTN: Mr. Coleman Nadler, Code 30221, AVTD Warminster, PA 18974

Defense Documentation Center (12) Cameron Station Alexandria, VA 22314 Dr. Robert S. Shane, Staff Scientist National Materials Advisory Board National Academy of Sciences 2101 Constitution Avenue, N.W. Washington, DC 20418

Technical Library ATTN: DRDAR-CLJ-L Aberdeen Proving Ground, MD 21010

Technical Library
ATTN: DRDAR-TSB-S
Aberdeen Proving Ground, MD 21005

Director U.S. Army TRADOC Systems Analysis Activity ATTN: ATAA-SL (Technical Library) White Sands Missile Range, NM 88002

Weapon System Concept Team/CSL ATTN: DRDAR-ACW Aberdeen Proving Ground, MD 21010

U.S. Army Materiel Systems Analysis Activity ATTN: DRXSY-MP Aberdeen Proving Ground, MD 21005